


VAPARS



Vapars, the Italian knock-off, has altered most of the key aspects of Magic Flight's design and in doing so, has drastically lowered efficiency and heat output. This product is still labeled a counterfeit because of the heat conducting mesh screen.




- 1 Full view of the Vapars unit.
- 2 Angled view to show unit width and screen mesh.
- 3 Inefficient screen design leads to unstable and inefficient heat.

- **Poor screen design:** Vapar's flat screen doesn't utilize infrared radiation, an effect caused by the trench in MFLB's screen design. This essential design element creates a zone of criticality leading to thorough heating of herbs. This omission could be the main factor in Vapar's inability to quickly or adequately heat up enough to produce satisfactory vapor.

- **Inadequate heat:** Another factor effecting the temperature is that the screen is not effectively bonded to any conduction metal. It's simply sandwiched between the two pieces of wood against the screen.

- **Comfort and safety:** The battery caps are very tight and awkward to remove. Also, the long width of the unit in comparison to the length of the battery makes it difficult to remove battery during heating, especially for medical patients with limited dexterity. Also, in eliminating the push-back ring, the battery can get stuck in the engaged position and become very hot. This can lead to irreversible battery damage.

TEMPERATURE TRIALS



<http://www.magic-flight.com/counterfeit-page.php>